



ಕರ್ನಾಟಕ ಸರ್ಕಾರ

(Public Works Port & Inland Water Transport Department)

No:EE/PWD/MYS/JE-2/2017-18/

/Dated:

O/o The Executive Engineer,
PWP & IWT Department,
Mysore Division, Vinobha Road,
Mysore.

To,

The Principal,
Eshwar Vidyalaya,
Choranahalli, Varuna Hobli,
Mysore Tq, Mysore Dist.

Sir,

Sub: Building safety certificate – Reg.

- Ref: 1)Your's ltr No: Nil/ dated:15-05-2017.
2)This Office ltr No: 1190/dated:23-05-2017.
3)Assistant Executive Engineer, No:2 Spl, PWD Sub-division,
Mysore ltr No: 514/2017-18/dated: 07-06-2017.

With reference to the above subject, you have requested to issue Building Safety certificate regarding your's school building. Constructed at Choranahalli Village in Varuna Hobli.

The Assistant Executive Engineer, No: 2 Spl, PWD Sub-division, Mysore has inspected your school & reported as follows:

- 1)The building is having ground & Ist floor with R.C.C roof is in good condition.

As per the report of Assistant Executive Engineer, No: 2 Spl, PWD Sub-division, Mysore it is certified that the building is in Good condition. It is also suggested that proper maintenance works of the building should be done periodically.

Thanking you,

Your's faithfully,

Executive Engineer,
PWP & IWT Department,
Mysore Division, Mysore.

for Eshwar Educational Trust (K)

B. Veera
Secretary

Principal
Eshwar Vidyalaya
Choranahalli, Varuna Hobli
Mysore Taluk